
PRIOR ART
BATCH MATERIALS
BLENDER
10
MELTING FURNACE
12
PLATINUM BUSHINGS
14
16
BINDER APPLICATION
20
COATING
18
WINDER
22
24
24
26
DRYING AND CURING
28
YARN TWISTING PROCESS
30
WARPING
YARNS
TEXTURIZING

Fig. 1



Fig. 2.



Fig. 3.



Fig. 4.



Fig. 5.